

DOMESTIC ELECTRICAL INSTALLATION

CONDITION REPORT Requirements For Electrical Installations - BS 7671 IET Wiring Regulations

Report Reference:

50012301

| DETAILS OF THE PERSON ORDERING THE REPORT Client: CONDOR PROPERTIES |
|--|
| Address: MILL HOUSE, LUGG BRIDGE MILL, HEREFORD, HR1 3NA |
| PREASON FOR PRODUCING THIS REPORT Reason for producing this report: Landlords safety report. |
| Date(s) on which inspection and testing was carried out: 30/05/2022 |
| 3 DETAILS OF THE INSTALLATION WHICH IS THE SUBJECT OF THIS REPORT |
| Installation Address: 20 ROSEHILL TERRACE, SWANSEA, SA1 6JN |
| Estimated age of wiring system: 15 years Evidence of additions/ alterations: No if yes, estimated age: 3 year Installation records available? (Regulation 651.1) Yes Date of last inspection: 23/07/2020 |
| EXTENT AND LIMITATIONS OF INSPECTION AND TESTING Extent of the electrical installation covered by this report: 100% of the installation. |
| Agreed limitations including the reasons (see Regulation 653.2): No Lifting of floor boards or inspection of loft space. INSULATION RESISTANCE TAKEN BETWEEN LINE AND CPC CONDUCTORS ONLY |
| Agreed with: |
| Operational limitations including the reasons: NONE |
| The inspection and testing detailed in this report and accompanying schedules have been carried out in accordance with BS 7671:2018 (IET Wiring Regulations) as amended to 2020. It should be noted that cables concealed within trunking and conduits, under floors, in roof spaces, and generally within the fabric of the building or underground, have not been inspected unless specifically agreed between the client and inspector prior to the inspection. An inspection should be made within an accessible roof space housing other electrical equipment. |
| 5 SUMMARY OF THE CONDITION OF THE INSTALLATION |
| See page 3 for a summary of the general condition of the installation in terms of electrical safety. Overall assessment of the installation in terms of it's suitability for continued use*: * An unsatisfactory assessment indicates that dangerous (Code C1) and/or potentially dangerous (Code C2) conditions have been identified. |
| RECOMMENDATIONS Where the overall assessment of the suitability of the installation for continued use on page 1 is stated as 'UNSATISFACTORY', I/We recommend that any observations classified as 'Code 1 - Danger Present' or 'Code 2 - Potentially dangerous' are acted upon as a matter of urgency. Investigation without delay is recommended for observations identified as 'FI - Further Investigation Required'. Observations classified as 'Code 3 - Improvement recommended' should be given due consideration. Subject to the necessary remedial action being taken, I/we recommend that the installation is further inspected and tested by: Note: The proposed date for the next inspection should take into consideration the frequency and quality of maintenance that the installation can reasonably be expected to receive during its intended life. The period should be agreed between relevant parties. |

| | | TONS FOR ACTIONS TO BE TAKEN | |
|-----------|---|---|-----------------------------|
| | | and test results, and subject to the limitations specif | ied on page 1 |
| | eport under 'Extent of the Installation and here are no items adversely affecting electrical | | |
| | | or | |
| N/A Tł | ne following observations and recommendations | s are made | |
| Item No | | Observations | Classification Code |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | e following codes, as appropriate, has been allo le for the installation the degree of urgency for | ocated to each of the observations made above to indicate to remedial action. | the person(s) |
| Risk | ger PresentC2Potentially dateof injury. ImmediateUrgent remediateedial action requiredrequired | | vestigation ithout delay |
| Immedia | te remedial action required for items: | N/A | |
| Urgent r | emedial action required for items: | N/A | |
| Improve | ment recommended for items: | N/A | |
| Further i | nvestigation required for items: | N/A | |

This form is based on the model shown in Appendix 6 of BS 7671:2018.

| 6 GENERA | | | ON OF TH | | | | | | | | | | | | | | | | |
|---|---|---|---|---------------------|-----------------------|---------------------|----------------------|------------------------------|-----------------------|---------------------|--------------------------|-----------------------|--------------------|-----|--|--|--|--|--|
| | | | | | | - | | | | | | тготи | | | | | | | |
| THE SYSTEM | IS GENE | KALL Y | IN A GOOD | COND | | WITH G | JOOD F | (ECORDS) | OF MAI | INTENA | NCE ANL |) IESIII | NG | | | | | | |
| 9 DECLAR | ATION | | | | | | | | | | | | | | | | | | |
| I/We, being the signatures below inspection and the provides an accu- in section 4 of the Trading Title: | ne person v), partic esting, h urate ass | i(s) resp ulars of ereby de essmen | which are de eclare that th t of the cond | escribed | above, nation ii | having n this re | exercis eport, ir | ed reasona Icluding the | ble skill e observ | and car ations a | e when ca Ind the att | arrying o ached so | ut the chedules | | | | | | |
| Address: | | s Line | | | | | | Registra (if appli | | Imber | 12345 | 6789 | | | | | | | |
| | | s Line : s Line : | | | | | | Telepho | | nber: | 01234 | 56789 | 01 | | | | | | |
| | | | | Postcode: POST CODE | | | | | | | | | | | | | | | |
| For the INSPE | CTION, 1 | FESTIN | G AND ASSI | ESSMEI | NT of th | ne repo | rt: | | | | | | | | | | | | |
| | Barrie Ta | | Positio | | alified | - | | ignature: | | -hp | - | Date: 3 | 0/05/2 | 022 | | | | | |
| 10 TEST IN | STRUN | ΛΕΝΤ | 5 | | | | | | | | | | | | | | | | |
| Details of Test | : Instrum | ents use | ed (state ser | al and/ | or asset | numbe | rs): | | | | | | | | | | | | |
| Multi-functional: | | | 429910 | 8 | | Eart | N/A | | | | | | | | | | | | |
| Insulation resist | ance: | | N/A | | | Eart | h fault | loop imped | ance: | | | N/A | | | | | | | |
| Continuity: | | | N/A | | | RCD |): | | | | | N/A | | | | | | | |
| | CHAR | ACTE | RISTICS | AND E | ARTH | I NG A | | IGEMEN | TS | | | | | | | | | | |
| Earthing Arrangements | ı | Number | and Type of L | ive | | Nat | ture of S | Supply Para | meters | | Supply | / Protect | ctive Device | | | | | | |
| TN-S 🖌 | 1-phase (2 wire) | | onductors 1-pha (3 wir | se e): N | I/A ' | ominal oltage(s | U: | 240 V L | Jo: 23 | 30 v | BS(EN): | 1361 | Fuse H | BC | | | | | |
| tn-c-s N/A | 3-phase (3 wire) | N/A | 2 nh2 | se N | I/A | | | requency, | f: 5(|) Hz | Туре: | | 2 | | | | | | |
| | Other: | | N/A | , | | | ospecti irrent, l | ve fault pf: | 1. | 2 kA | Rated cu | | 60 | A | | | | | |
| TT N/A | Confirm | ation of | supply polar | ity: | ✓ | | | earth fault edance, Ze: | 0.2 | 20 Ω ¦ | Short-cir capacity: | cun | 33 | kA | | | | | |
| 12 PARTIC | ULARS | OF I | VSTALLA | ION | REFER | RRED | ΤΟΙΝ | THE RE | PORT | | | | | | | | | | |
| Means of Earth | | 1 | | | | | | Electrode (| | applicabl | le) | | | | | | | | |
| Distributor's facility: | ~ | T T | ype: | | N/A | L | ocatior | ı: | | | N/A | | | | | | | | |
| Installation earth electrode: | N// | Λι | esistance Earth: | N/A | Ω | | Method measure | | | | N/A | | | | | | | | |
| Maximum Dema | ind (Load |): | 60 Amps | | ctive me st electr | • | | ۲ | ADS | | | | | | | | | | |
| Main Switch / Sv | vitch-Fus | e / Circ | uit-Breaker / | RCD | | c | Supply | | | If RCD | main swit | :ch: | | | | | | | |
| Type BS(EN): 6094 | 47-3 Isol | olator Current rati | | t rating: 1 | | | conduct | ors Co | pper | | residual | (14n) | N/A | mA | | | | | |
| Number of poles: 2 | | | Fuse/device or setting: | rating | N/A | Λ | materia Supply | : | | | ing currer time delag | | N/A | ms | | | | | |
| | | | Voltage ratin | ng: | 240 | V | conduct | ors 25 | mm ² | | red opera at l∆n): | ting | N/A | ms | | | | | |
| Earthing and Pro Earthing conduc | | onding | Conductors | Cor | nection | / | | ding of extr vater instal | | -conduc | | installat | ion | | | | | | |

csa:

csa:

Conductor

material:

Conductor

material:

Copper

Copper

Main protective bonding conductors

16 mm² continuity

10 mm² continuity

verified:

verified:

Connection/

pipes:

pipes:

steel:

To oil installation

To structural

1

1

~

pipes: To lightning

protection: To other service(s):

N/A

N/A mA N/A ms

N/A ms - - - - - - - -

| 3 11 | ISPECTION SCHEDULE FOR DOMESTIC & SIMILAR PRE | MISES WITH UP TO 100A S | UPPLY |
|------------------------------|---|---|----------------------------|
| Item | Description | Comments | Outcome |
| 1.0 | EXTERNAL CONDITION OF INTAKE EQUIPMENT (VISUAL INSPECTI | ON ONLY) | |
| 1.1 | Service cable | N/A | Pass |
| 1.2 | Service head | N/A | Pass |
| 1.3 | Earthing arrangement | N/A | Pass |
| 1.4 | Meter tails | N/A | Pass |
| 1.5 | Metering equipment | N/A | Pass |
| 1.6 | Isolator (where present) | N/A | N/A |
| 2.0 | PRESENCE OF ADEQUATE ARRANGEMENTS FOR OTHER SOURCES SUCH AS MICROGENERATORS (551.6; 551.7) | N/A | N/A |
| 3.0 | EARTHING / BONDING ARRANGEMENTS (411.3; Chap 54) | | |
| 3.1 | Presence and condition of distributor's earthing arrangement (542.1.2.1; 542.1.2.2) | N/A | Pass |
| 3.2 | Presence and condition of earth electrode connection where applicable (542.1.2.3) | N/A | N/A |
| 3.3 | Provision of earthing/bonding labels at all appropriate locations (514.13.1) | N/A | Pass |
| 3.4 | Confirmation of earthing conductor size (542.3; 543.1.1) | N/A | Pass |
| 3.5 | Accessibility and condition of earthing conductor at MET (543.3.2) | N/A | Pass |
| 3.6 | Confirmation of main protective bonding conductor sizes (544.1) | N/A | Pass |
| 3.7 | Condition and accessibility of main protective bonding conductor connections (543.3.2; 544.1.2) | N/A | Pass |
| 3.8 | Accessibility and condition of other protective bonding connections (543.3.1; 543.3.2) | N/A | Pass |
| 4.0 | CONSUMER UNIT(S) / DISTRIBUTION BOARD(S) | 1 | |
| 4.1 | Adequacy of working space/accessibility to consumer unit/distribution board (132.12; 513.1) | HIGH LEVEL | Pass |
| 4.2 | Security of fixing (134.1.1) | N/A | |
| 4.3 | Condition of enclosure(s) in terms of IP rating etc (416.2) | SOME GAPS BUT ENCLOSED IN FIRE RATED ENCLOSURE | Pass |
| 4.4 | Condition of enclosure(s) in terms of fire rating etc (421.1.201; 526.5) | PLASTIC BUT IN FIRE RATED ENCLOSURE | |
| 4.5 | Enclosure not damaged/deteriorated so as to impair safety (651.2) | N/A | Pass |
| 4.6 | Presence of main linked switch (as required by 462.1.201) | N/A | N/A |
| 4.7 | Operation of main switch (functional check) (643.10) | N/A | Pass |
| 4.8 | Manual operation of circuit-breakers and RCDs to prove disconnection (643.10) | N/A | Pass |
| 4.9 | Correct identification of circuit details and protective devices (514.8.1; 514.9.1) | N/A | Pass |
| 4.10 | Presence of RCD six-monthly test notice at or near consumer unit/distribution board (514.12.2) | OLD LABEL IN PLACE BUT REPLACED FOR NEW TYPE | Pass |
| 4.11 | Presence of non-standard (mixed) cable colour warning notice at or near consumer unit/distribution board (514.14) | N/A | Pass |
| 4.12 | Presence of alternative supply warning notice at or near consumer unit/distribution board (514.15) | N/A | N/A |
| 4.13 | Presence of other required labelling (please specify) (Section 514) | N/A | Pass |
| 4.14 | Compatibility of protective devices, bases and other components; correct type and rating (No signs of unacceptable thermal damage, arcing or overheating) (411.3.2; 411.4; 411.5; 411.6; Sections 432, 433) | N/A | Pass |
| UTCON Accepta conditio | ble Unacceptable Improvement C2 Further | verified N/V Limitation LIM appl | Not icable Page: 4 c |

| <u>4 IN</u> | ISPECTION SCHEDULE FOR DOMESTIC & SIMILAR PRE | INTSES WITH UP TO 100A S | UPPLY |
|--------------------------------|---|---------------------------------------|-----------------------------|
| Item | Description | Comments | Outcome |
| 4.15 | Single-pole switching or protective devices in line conductor only (132.14.1; 530.3.3) | N/A | Pass |
| 4.16 | Protection against mechanical damage where cables enter consumer unit/distribution board (132.14.1; 522.8.1; 522.8.5; 522.8.11) | N/A | Pass |
| 4.17 | Protection against electromagnetic effects where cables enter consumer unit/distribution board/enclosures (521.5.1) | N/A | N/A |
| 4.18 | RCD(s) provided for fault protection - includes RCBOs (411.4.204; 411.5.2; 531.2) | N/A | N/A |
| 4.19 | RCD(s) provided for additional protection/requirements - includes RCBOs (411.3.3; 415.1) | N/A | Pass |
| 4.20 | Confirmation of indication that SPD is functional (651.4) | N/A | N/A |
| 4.21 | Confirmation that ALL conductor connections, including connections to busbars, are correctly located in terminals and are tight and secure (526.1) | N/A | Pass |
| 4.22 | Adequate arrangements where a generating set operates as a switched alternative to the public supply (551.6) | N/A | N/A |
| 4.23 | Adequate arrangements where a generating set operates in parallel with the public supply (551.7) | N/A | N/A |
| 5.0 | FINAL CIRCUITS | | |
| 5.1 | Identification of conductors (514.3.1) | N/A | Pass |
| 5.2 | Cables correctly supported throughout their run (521.10.202; 522.8.5) | N/A | Pass |
| 5.3 | Condition of insulation of live parts (416.1) | N/A | Pass |
| 5.4 | Non-sheathed cables protected by enclosure in conduit, ducting or trunking (521.10.1) | N/A | N/A |
| 5.4.1 | To include the integrity of conduit and trunking systems (metallic and plastic) | N/A | Pass |
| 5.5 | Adequacy of cables for current-carrying capacity with regard for the type and nature of installation (Section 523) | N/A | Pass |
| 5.6 | Coordination between conductors and overload protective devices (433.1; 533.2.1) | N/A | Pass |
| 5.7 | Adequacy of protective devices: type and rated current for fault protection (411.3) | N/A | Pass |
| 5.8 | Presence and adequacy of circuit protective conductors (411.3.1; Section 543) | N/A | Pass |
| 5.9 | Wiring system(s) appropriate for the type and nature of the installation and external influences (Section 522) | N/A | Pass |
| 5.10 | Concealed cables installed in prescribed zones (see Section 4. Extent and Limitations) (522.6.202) | N/A | Pass |
| 5.11 | Cables concealed under floors, above ceilings or in walls/partitions, adequately protected against damage (see Section 4. Extent and Limitations) (522.6.204) | N/A | Pass |
| 5.12 | Provision of additional requirements for protection by RCD not exc | ceeding 30mA: | 1 |
| 5.12.1 | For all socket-outlets of rating 32A or less, unless an exception is permitted (411.3.3) | N/A | Pass |
| 5.12.2 | For the supply of mobile equipment not exceeding 32A rating for use outdoors (411.3.3) | N/A | Pass |
| 5.12.3 | For cables concealed in walls at a depth of less than 50mm (522.6.202; 522.6.203) | FIRE ALARM PANEL NOT PROTECTED BY RCD | C3 |
| 5.12.4 | For cables concealed in walls/partitions containing metal parts regardless of depth (522.6.203) | N/A | LIM |
| 5.12.5 | Final circuits supplying luminaires within domestic (household) premises (411.3.4) | N/A | Pass |
| OUTCON Acceptal conditio | ble Unacceptable Improvement C2 Further | verified N/V Limitation LIM appli | ot cable N/ Page: 5 o |

| 1 <u>5 IN</u> | ISPECTION SCHEDULE FOR DOMESTIC & SIMILAR PRE | MISES WITH UP TO 100A S | UPPLY |
|--------------------------------|--|--|-------------|
| Item | Description | Comments | Outcome |
| 5.13 | Provision of fire barriers, sealing arrangements and protection against thermal effects (Section 527) | N/A | Pass |
| 5.14 | Band II cables segregated/separated from Band I cables (528.1) | N/A | LIM |
| 5.15 | Cables segregated/separated from communications cabling (528.2) | N/A | LIM |
| 5.16 | Cables segregated/separated from non-electrical services (528.3) | N/A | LIM |
| 5.17 | Termination of cables at enclosures - indicate extent of sampling in (Section 526) | n Section 4 of the report | |
| 5.17.1 | Connections soundly made and under no undue strain (526.6) | N/A | Pass |
| 5.17.2 | No basic insulation of a conductor visible outside enclosure (526.8) | N/A | Pass |
| 5.17.3 | Connections of live conductors adequately enclosed (526.5) | N/A | Pass |
| 5.17.4 | Adequately connected at point of entry to enclosure (glands, bushes etc.) (522.8.5) | N/A | Pass |
| 5.18 | Condition of accessories including socket-outlets, switches and joint boxes (651.2(v)) | N/A | Pass |
| 5.19 | Suitability of accessories for external influences (512.2) | N/A | Pass |
| 5.20 | Adequacy of working space/accessibility to equipment (132.12; 513.1) | N/A | Pass |
| 5.21 | Single-pole switching or protective devices in line conductors only (132.14.1, 530.3.3) | N/A | Pass |
| 6.0 | LOCATION(S) CONTAINING A BATH OR SHOWER | | |
| 6.1 | Additional protection for all low voltage (LV) circuits by RCD not exceeding 30mA (701.411.3.3) | N/A | Pass |
| 6.2 | Where used as a protective measure, requirements for SELV or PELV met $(701.414.4.5)$ | N/A | Pass |
| 6.3 | Shaver sockets comply with BS EN 61558-2-5 formerly BS 3535 (701.512.3) | N/A | Pass |
| 6.4 | Presence of supplementary bonding conductors, unless not required by BS 7671:2018 (701.415.2) | N/A | N/A |
| 6.5 | Low voltage (e.g. 230 volt) socket-outlets sited at least 3m from zone 1 (701.512.3) | N/A | N/A |
| 6.6 | Suitability of equipment for external influences for installed location in terms of IP rating (701.512.2) | N/A | Pass |
| 6.7 | Suitability of accessories and controlgear etc. for a particular zone (701.512.3) | N/A | Pass |
| 6.8 | Suitability of current-using equipment for particular position within the location (701.55) | N/A | Pass |
| 7.0 | OTHER PART 7 SPECIAL INSTALLATIONS OR LOCATIONS | ataly the results of particular inspection | |
| 7.1 | | | |
| 7.2 | | | |
| 7.3 | | | |
| 7.4 | | | |
| 7.5 | | | |
| 7.6 | | | |
| 7.7 | | | |
| 7.8 | | | |
| 7.9 | | | |
| 7.10 | | | |
| 7.10 | Provision of fire barriers, sealing arrangements and protection against thermal effects (Section 527) Band II cables segregated/separated from Rand I cables (S28.1) A/A Cables segregated/separated from non-electrical services (S28.3) A/A Cables segregated/separated from non-electrical services (S28.3) A/A Carbon of cables at enclosures - indicate extent of sampling in Section 4 of the report (Section 520) Connections soundy made and under no undue strain (S26.6) A/A No basic insulation of a conductor visible outside enclosure (S26.8) A/A Connections of live conductors adequately enclosed (S26.5) A/A Connections of live conductors adequately enclosed (S26.5) A/A Connections of live conductors adequately enclosed (S26.5) A/A Adequately connected at point of entry to enclosure (glands, bushes etc.) N/A Condition of accessories for external influences (S12.2) N/A Adequately of working space/accessibility to equipment (S12.12) Suitability of accessories for external influences (S12.2) N/A Adequately of working space/accessibility to equipment for SELV or PELV met Additional protection for all low voltage (LV) arcuits by RCD not Exceeding 30mA (201 411 3.3) N/A Construction for all low voltage (LV) arcuits by RCD not Exceeding 30mA (201 411 3.3) N/A Presence of supplementary bonding conductors, unless not required by N/A Presence of supplementary bonding conductors, unless not required by N/A Suitability of equipment for external influences for installed location in N/A Suitability of equipment for external influences for installed location in N/A Suitability of equipment for particular position within the Incation (201 55) DTHER PART 7 SPECIAL INSTALLATIONS OR LOCATIONS ISTAL INSTALLATIONS OR LOCATIONS I | | |
| OUTCOM Acceptal conditio | ble Unacceptable Improvement Further | | ot cable |

| Desi | SCHEDULE OF CIRCUIT DETA ignation of mer unit: |).B. 1 | | | | | | Locatio | n: | | | CU | PBOA | rd at | MAIN | ENT | RANCI | Ξ | | | ospec rrent: | | fault | | 1.2 | ł |
|----------------|--|----------------|------------------|----------------------------|--|------------------------|---|-----------------------|-------------------|----------|----------------|--------------------------|---|--------------|---|----------------|----------|--|----------|------------------------|-----------------|------------------------------|--|-----------------------|--|---------------------------------|
| | | | a a | | Ciro condu cs | cuit ctors: a | t time S7671 | Overcurr | ent pi levice: | | ve | RCD | BS7671 | | Circuit im | bedance | | | | nsulation esistance | | | sured | RC | D | AFI |
| Circuit number | Circuit designation | Type of wiring | Reference Method | Number of points served | Circ condu cs Live mm ² | срс mm ² | Max disconnec permitted by B | BS(EN) | Type No | > Rating | Capacity | B Operating Current, IAn | b Maximum Z _S permitted by B | (measu | nal circui ured end ^r n (Neutral) | r ₂ | (one co | rcuits lumn to pleted) R ₂ | ΩM MB | ΩM DM | < Test voltage | Polarity | Maximum measured b earth fault loop impedance Zs | B Disconnection stime | Test button operation | Test button |
| 1 | Main Switch | | | | | | | | | | | | | | | | | | | | | | | | | |
| 2 | НОВ | A | С | 1 | 6 | 2.5 | 0.4 | 61009 | В | 32 | 6 | 30 | 1.37 | N/A | N/A | N/A | 0.16 | N/A | LIM | > 200 | 500 | ~ | 0.36 | 27.6 | r | N |
| 3 | Kitchen Sockets | А | С | 4 | 6 | 2.5 | 0.4 | 61009 | В | 32 | 6 | 30 | 1.37 | N/A | N/A | N/A | 0.25 | N/A | LIM | > 200 | 500 | ~ | 0.45 | 15.6 | ~ | Ν |
| 4 | REAR RING | А | С | 4 | 2.5 | 1.5 | 0.4 | 61009 | В | 32 | 6 | 30 | 1.37 | 0.48 | 0.48 | 0.79 | 0.28 | N/A | LIM | > 200 | 500 | ~ | 0.48 | 12.7 | ~ | N |
| 5 | FRONT RING | A | С | 6 | 2.5 | 1.5 | 0.4 | 61009 | В | 32 | 6 | 30 | 1.37 | 0.54 | 0.53 | 0.87 | 0.17 | N/A | LIM | > 200 | 500 | ~ | 0.37 | 21.2 | ~ | Ν |
| 6 | BACK BED SOCKETS | А | С | 5 | 2.5 | 1.5 | 0.4 | 61009 | В | 20 | 6 | 30 | 2.19 | N/A | N/A | N/A | 0.31 | N/A | LIM | > 200 | 500 | ~ | 0.51 | 18.2 | ~ | Ν |
| 7 | LIGHTS STAIRS AND ATTIC | А | С | 6 | 1.5 | 1.0 | 0.4 | 61009 | В | 6 | 6 | 30 | 7.28 | N/A | N/A | N/A | 0.48 | N/A | LIM | > 200 | 500 | ~ | 0.68 | 17.4 | ~ | Ν |
| 8 | LIGHTS OTHER | А | С | 7 | 1.5 | 1.0 | 0.4 | 61009 | В | 6 | 6 | 30 | 7.28 | N/A | N/A | N/A | 0.92 | N/A | LIM | > 200 | 500 | ~ | 1.12 | 24.1 | r | Ν |
| 9 | FIRE ALARM | 0 | С | 1 | 1.5 | 1.5 | 0.4 | 60898 | В | 6 | 6 | N/A | 7.28 | N/A | N/A | N/A | 0.08 | N/A | LIM | > 200 | 500 | ~ | 0.28 | N/A | N/A | Ν |
| 10 | Spare | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N |
| 11 | Spare | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N |
| | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | - |
| | | | | | | | | | | | | | | | | | | | | | | | | | | t |
| | | | | | | | | | | | | | | | | | | | | | | | | | | - |
| | | | | | | | | | | | | | | | | | | | | | | | | | | \vdash |
| | | | | | | | | | | | | | | | | | | | | | | | | <u> </u> | | ┢ |
| | | | | | | | | | | | | | | | | | | | | | | | | | | + |
| | | | | | | | | | | | | | | | | | | | | | | | | | | - |
| | AB | | | C | | | | D | | | E | | | F | | | G | | Н | | | | 0 - 0 | ther | | |
| | ES FOR Thermoplastic Thermoplast PE OF insulated/sheathed cables in | ic | | ermopl cables | | | | moplastic ables in | | | rmopl ables | | | г Thermop | olastic ables | Therr | nosettin | g | Miner | al | | | N/ | | | |

DOMESTIC ELECTRICAL INSTALLATION CONDITION REPORT GUIDANCE FOR RECIPIENTS

(to be appended to the Report)

This Report is an important and valuable document which should be retained for future reference.

 The purpose of this Report is to confirm, so far as reasonably practicable, whether or not the electrical installation is in a satisfactory condition for continued service (see Section 5). The Report should identify any damage, deterioration, defects and/or conditions which may give rise to danger.
 The person ordering the Report should have received the 'original' Report and the inspector should have retained a duplicate.

3. The 'original' Report should be retained in a safe place and be made available to any person inspecting or undertaking work on the electrical installation in the future. If the property is vacated, this Report will provide the new owner/occupier with details of the condition of the electrical installation at the time the Report was issued.

4. Where the installation incorporates a residual current device (RCD) there should be a notice at or near the device stating that it should be tested six-monthly. For safety reasons it is important that this instruction is followed.

5. Section 4 (Extent and Limitations) should identify fully the extent of the installation covered by this Report and any limitations on the inspection and testing. The inspector should have agreed these aspects with the person ordering the Report and with other interested parties (licensing authority, insurance company, mortgage provider and the like) before the inspection was carried out.

6. Some operational limitations such as inability to gain access to parts of the installation or an item of equipment may have been encountered during the inspection. The inspector should have noted these in Section 4.

7. For items classified in Section 7 as C1 ('Danger present'), the safety of those using the installation is at risk, and it is recommended that a skilled person or persons competent in electrical installation work undertakes the necessary remedial work immediately.

8. For items classified in Section 7 as C2 ('Potentially dangerous'), the safety of those using the installation may be at risk and it is recommended that a skilled person or persons competent in electrical installation work undertakes the necessary remedial work as a matter of urgency.

9. Where it has been stated in Section 7 that an observation requires further investigation (code FI) the inspection has revealed an apparent deficiency which may result in a code C1 or C2, and could not, due to the extent or limitations of the inspection, be fully identified. Such observations should be investigated without delay. A further examination of the installation will be necessary, to determine the nature and extent of the apparent deficiency (see Section 6).
10. For safety reasons, the electrical installation should be re-inspected at appropriate intervals by a

10. For safety reasons, the electrical installation should be re-inspected at appropriate intervals by a skilled person or persons, competent in such work. The recommended date by which the next inspection is due is stated in Section 6 of the Report under 'Recommendations' and on a label at or near to the consumer unit/ distribution board.