

Gas and heating specialists

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure.

Company / Installer						Job Address							Customer / Landlord							
Engineer	Steven Ballard				Name							Name								
Company	Ballards gas services Itd				Address	10	100					Compa	ny	Condor Properties						
Address	Address 201					St	ation Stre	eet				Addres	S	mill house						
	Sileby Road					Lo	Loughborough						Lugg Bridge Mill							
	-	arrow Upon Soar				Le	Leicestershire							Worcester Road						
		Leicestershire				LE	LE11 5EG							Hereford						
Post Code				Tel. No							Post Co	de	HR1 3NA							
Tel No.												Tel. No								
Gas Safe Reg	0,0000100,0																			
ID Card No.																				
Appliance [Inspection Details																		
Locatio	on	Appliance Type	Make	Mode	I Flue	Flue Type	Landlord's Appliance	rd's Appliance Inspected	Operating Pressure (mbar)	Heat Input (kW/h)	High Combusti Reading	Low Combustio Reading		on Safety device(s) correct	Provision	Visual condition of flue and	Performance	Appliance Serviced	Appliance safe to use	
											Ratio CO C ppm	O2 % Ratio	CO CC ppm %	02 operation	satisfactory	termination satisfactory	test			
1 Bedroo	oms	Combination Boiler	Ideal	Logic 3	30+	RS	Yes	Yes	22.5	28.25	0009 83 9	9.1 na			Yes	Yes	Pass	Yes	Yes	
2				.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		-														
3																				
4																				
5																				
6																				
Defects / lo	k		Labels and Warning Notice Issued						CO Alarm(s) Smok					Alarm(s))					
1										NA										
2												CO Ala	arm(s) fi	tted	Yes	Smoke /	Alarm(s) fitt	ed	NA	
3																				
4												CO Alarm(s) tested Pass and Satisfactory				Smoke Alarm(s) tested NA and Satisfactory				
6													lisiacto	,, y			Slactory			
Emergency C	Control Acc	cessible Yes Gas	Tightness Satisfactory Yes	s	Comm	ents						<u> </u>								
Gas Installation Pipework Visual Inspection Satisfactory Yes																				
	Equipotential Bonding Yes																			
Water quality	/level of i	nhibitor acceptable	NA																	
NEXT INSPE	NEXT INSPECTION DUE BEFORE 05-Aug-2025																			
Cignotures																				
Signatures Issued by: Signed <i>JBAMbul</i> Beceived Signed by: Date Date Dote																				
Print Name		Steven Ballard		F	Print Name															