

Landlord Gas Safety Record

Cert. No. 529

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations 1998 section 26(9) and the Gas

as.	s and neat	ing specia	alists					Industr	y Unsafe Situati	ons Procedure.													
Company / Installer							ress							Custon	ner /	Landlord							
En	gineer	Steven Ballard				Name								Name									
Company Address		Ballards gas services ltd 201				Address	19	98							Company		Condor Properties						
							As	shby Road	l					Address		mill house							
		Sileby Road Barrow Upon Soar					Lo	oughborou	ıgh							Lugg Bridge Mill Worcester Road							
							Le	eicestersh	ire														
		Leicestershire				Post Code	e LE	E11 3AG								Hereford							
Post Code Tel No.		LE12 8LP 07599610379				Tel. No								Post Code	de	HR1 3NA							
															Tel. No								
Ga	s Safe Reg	527987																					
ID	Card No.																						
αA	pliance D	etails						Inspec	tion Details														
Locatio		Appliance Type		Make	Mode	el	Flue Type	Landlord's		Operating Pressure	Heat Input (kW/h)							Visual condition		Appliance	Appliance safe		
								Appliance		(mbar)		Reading Ratio CO (Reading CO2 Ratio CO CO		correct operation	Provision satisfactory	of flue and termination	Performance test	Serviced	to use		
_	DI 1 D				1 1 . 6	. 20	D.C.			22	27.25		ppm %		ppm	%		satisfactory		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \			
1	Plant Roo	om C	entral Heating Boiler	Ideal	Logic + Sy	stem 30	RS	Yes	Yes	22	27.35	0009	8/ 9.	3 0003	14 8	3.6 Yes	Yes	Yes	Pass	Yes	Yes		
2	Kitcher	ı	Hob	Nk	Nk	(NA	Yes	Yes	23	NA	NA	NA N	A NA	NA N	IA Yes	Yes	NA	NA	NA	Yes		
3																							
4																							
5																							
6																							
De	fects / Ide	entified								Labels a	ind Warning No	otice Iss	sued	CO Ala	rm(s	5)		Option	al Check	S			
1											NA				CO Alarm(s) fitted Yes			Smoke Alarm(s) fitted NA					
	2	Hob rings need deep clean from grease.							NA														
3											CO Alarm(s) tested and Satisfactory Pass			Pass	Smoke Alarm(s) tested and Satisfactory								
4 5 6											and Satisfactory				and Sat	and Satisfactory							
																	Water quality/level of inhibitor						
																		accepta			" NA		
En	organsy Co.	atral Accas	sible Ves	T' 1 C 1' C 1 Y		Comi	ments																
EII	lergency cor	ILIUI ACCES	sible les Gas	Tightness Satisfactory Yes	S																		
Ga	s Installation	n Pipework	Visual Inspection	Satisfactory Yes		Tigh	tness te	st carried	out after inter	nal Ecv													
	Equipotenti	al Bonding	Yes																				
NE	XT INSPEC	TION DUE	BEFORE	07-Aug-2026																			
Sic	natures																						
	ued by:	Signed	10	,	F	Received :	Sianed							Date		07	-Aug-2025						
			Malla	2.1		24.	- J									07							

Print Name

Steven Ballard

Print Name