

Landlord Gas Safety Record

Cert. No. 543

Gas and heating specialists

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure.

Company / I		Job Addr	ess						Customer	/ Landlord									
Engineer	Steven Ba	Steven Ballard				ame						Name							
Company	Ballards g	Address 20							Company										
Address 201					Broad Street							Address	mill house						
	Sileby Ro	ad				Lo	Loughborough						Lugg Bridg	Lugg Bridge Mill					
Barrow Upon Soar				Post Code		Leicestershire						Worcester	Worcester Road						
	Leicesters	Leicestershire				LE	LE11 5AB						Hereford	Hereford					
Post Code LE12 8LP				Tel. No							Post Code	HR1 3NA							
Tel No.	07555010575											Tel. No							
Gas Safe Reg	as Safe Reg 527987																		
ID Card No.																			
Appliance Details Inspection Details																			
Location Appliance Type Make Mod					el	Flue Type				Heat Input (kW/h)	High Combust	tion Low Combus	tion Safety device	s) Ventilation	Visual conditio	n Flue	Appliance	Appliance safe	
							Appliance		(mbar)	,	Reading	Reading	correct	Provision satisfactory	of flue and	Performance test	Serviced	to use	
											Ratio CO ppm	CO2 % Ratio CO ppm	CO2 %	,	satisfactory				
1 Bedroor	ms Co	mbination Boiler	Glow-worm	240	i	RS	Yes	Yes	21.75	22.75	0011 81	8.9 na na	na Yes	Yes	Yes	Pass	Yes	Yes	
2																			
3																			
4																			
5																			
6													_		_		_		
Defects / Identified									Labels and Warning Notice Issued				CO Alarm(s)				Smoke Alarm(s)		
1										NA		CO Alama(a)	Elst and	Vaa	Cmarka	Alama(a) fit	t a al	NIA	
2												CO Alarm(s)	iiiteu	Yes	Silloke	Alarm(s) fit	teu	NA	
4												CO Alarm(s) tested			Smoke Alarm(s) tested				
5											and Satisfac		Pass		tisfactory		NA		
6																			
Emergency Co	ntrol Acces	ssible Yes Gas	Tightness Satisfactory Ye	S	Comn	nents													
Gas Installation Pipework Visual Inspection Satisfactory Yes																			
	·		outlibration, res																
Equipotential Bonding Yes																			
Water quality/l	level of inh	ibitor acceptable	NA																
NEXT INSPEC	TION DUE	REFORE	05-Aug-2025																
NEXT INSTEE	THOM DOL	. DEI ORE																	
Signatures	Ci-			_								D. I	0=						
Issued by:	Signed	Balle	21/		Received S by:	igned						Date	05-	Aug-2024					
		J_W/VCli	M	ı.	, y .														
Print Name		Steven Ballard		P	Print Name														