

Print Name

Steven Ballard

## **Landlord Gas Safety Record**

Cert. No. 528

Gas and heating specialists

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure.

		J - I-							Situations Proc	edure.													
Coı	mpany / I	nstall	er			Job Addr	ess							Cus	tome	r/L	andlord						
Engineer		Steven Ballard				Name																	
Company		Ballards gas services ltd				Address	20	200							npany		Condor Properties						
Address		201 Sileby Road Barrow Upon Soar Leicestershire				Post Code	As	hby Road	d					Addre	lress		mill house						
							Lo	Loughborough									Lugg Bridge Mill						
								icestersh							V		Worcester Road						
							LE	11 3AG									Hereford						
Post Code		LE12 8LP				Tel. No								t Code									
Tel No.		07599610379												Tel.	No								
Gas Safe Reg																							
ID Card No.		521301																					
Apı	oliance D					nspection Details																	
	Location		Appliance Type	Make	Mode	el	Flue Type	Landlord's Appliance	Appliance Inspected	Operating Pressure (mbar)	Heat Input (kW/h)	High Combusti Reading		ion Low Combustic Reading			correct	Provision	Visual condition of flue and	Performance	Appliance Serviced	Appliance safe to use	
												Ratio	CO C	CO2 % F	O2 % Ratio CO CO		operation	satisfactory	termination satisfactory	test			
1	Kitcher	n	Hob	Beko	Nk		NA	Yes	Yes	21	NA	NA		NA	NA NA	_	Yes	Yes	NA	NA	NA	Yes	
2	Loft		Combination Boiler	Ideal	Logic 3	30+	RS	Yes	Yes	22	28.75	0009	84	9.2	na na	na	Yes	Yes	Yes	Pass	Yes	Yes	
3																							
4																							
5																							
6																							
Defects / Identified								Labels and Warning Notice Issued						CO Alarm(s)				Smoke Alarm(s)					
	1										NA												
2								NA				CO Alarm(s) fitted Yes			Yes	Smoke Alarm(s) fitted NA							
3														CO Alarm(s) tested					Smoke Alarm(s) tested				
5													and Satisfactory			Pass	and Satisfactory						
6																							
Emergency Control Accessible Yes Gas Tightness Satisfactory Yes Comments																							
Gas Installation Pipework Visual Inspection Satisfactory Yes																							
Sas installation (parton risas inspection autorition)																							
Equipotential Bonding Yes																							
Water quality/level of inhibitor acceptable NA																							
NEXT INSPECTION DUE BEFORE 05-Aug-2025																							
MEAT INST ECTION DOE DET ONE OF MAY 2023																							
	natures																						
Issi	ued by:	Signe	d Balla	21/		teceived S y:	Signed								Date		05-Aı	ıg-2024					
			1 NVV Cli	cu	L	у.																	

Print Name