

Gas and heating specialists

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure.

Company / Installer							Job Address							Customer / Landlord						
Engineer Company Address Post Code		Steven Ba	Name							Name										
		Ballards gas services ltd 201 Sileby Road				Address	s 41					Company	Condor Properties							
							Ro	Roseberry Street					Address	mill house						
							Lo	Loughborough						Lugg Bridge Mill						
		Barrow Upon Soar					Lei	Leicestershire						Worcester Road						
		Leicestershire				Post Code	LE	LE11 5DX						Hereford						
		LE12 8LP				Tel. No							Post Code	HR1 3NA						
Tel No.		07599610379											Tel. No							
Gas Safe Reg																				
ID	Card No.																			
۸n	pliance D	otails						Incher	tion Details											
Αþ	Location		1	Flue Type		Appliance Inspected	Operating Pressure	Heat Input (kW/b)	High Combusti	on Low Combustion	Safety device(s	Ventilation	Visual condition	Flue	Appliance	Appliance safe				
	Location		Appliance Type	Make	Mode		luc Type	Appliance	hpphanee inspected	(mbar)	fielde input (itti),i)	Reading	Reading	correct	Provision satisfactory	of flue and termination	Performance test	Serviced	to use	
													CO2 Ratio CO CO % Ppm %	4		satisfactory				
1	Kitcher	n Co	mbination Boiler	Ideal	Logic 30) Max	RS	Yes	Yes	22	29.5	0007 112	9.1 0001 17 8.	7 Yes	Yes	Yes	Pass	Yes	Yes	
2																				
3																				
4																				
5																				
6																		-		
De	fects / lde	entified						Labels and Warning Notice Issued					CO Alarm(s	Smoke	Smoke Alarm(s)					
	1										NA									
	2												CO Alarm(s) fi	tted	Yes	Smoke /	Alarm(s) fitt	ed	NA	
	3												CO Alarm(s) te	stad		Smoke	Alarm(s) tes	tod		
	5												and Satisfacto		Pass	and Sati		leu	NA	
	6																			
Em	nergency Cor	ntrol Acces	sible Yes Gas	Tightness Satisfactory Ye	S	Comm	ents													
Ga	s Installation	n Pipework	Visual Inspection	Satisfactory Yes																
Gas Installation Pipework Visual Inspection Satisfactory Yes																				
Equipotential Bonding Yes																				
Water quality/level of inhibitor acceptable NA																				
NE	EXT INSPEC	TION DUE	BEFORE	05-Aug-2025																
	noturoe																			
	gnatures sued by:	Signed				Received Si	bong						Date		ug 2024					
155	ueu by:	Signed	Balla			y:	yneu						Date	05-A	ug-2024					
			1 NVV et		~															
Pri	int Name		Steven Ballard		P	rint Name														