

Landlord Gas Safety Record

Cert. No. 524

Gas and heating specialists

Steven Ballard

Print Name

Print Name

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure.

Compa	ny / Inst	aller				Job Addı	ress						Customer / I	andlord					
Enginee	Ste	ven Ballard				Name							Name						
Compan	y Bal	Ballards gas services ltd				Address	Address 55						Company	Condor Properties					
Address		201 Sileby Road					Ra	Radmoor Road Loughborough				Address	mill house Lugg Bridge Mill						
	Sile						Lo												
		Barrow Upon Soar					Le	icestersh	ire					Worcester F	Road				
		Leicestershire					e LE	LE11 3BP					Hereford						
Post Cod		LE12 8LP				Tel. No	Tel. No							HR1 3NA					
Tel No.	07599610379											Tel. No							
Gas Safe	5 Safe Reg 527987																		
ID Card I		321301																	
		_								1									
	ce Deta	ls							tion Details										
	Location	Appliance Type	М	Make		I Flue 1	Flue Type	Landlord's Applian Appliance	Appliance Inspected	pected Operating Pressur (mbar)	e Heat Input (kW/h)	Reading	Reading	correct	Ventilation Provision satisfactory	Visual condition of flue and termination	Performance test	Appliance Serviced	Appliance safe to use
												Ratio CO (CO2 Ratio CO CO % ppm %	2	,	satisfactory			
1 Airin	g Cupboard	d Central Heating Boiler	Id	deal	Logic Max S	ystem 24	RS	Yes	Yes	20.5	20.25	0008 79 9	9.4 0001 15 8.	8 Yes	Yes	Yes	Pass	Yes	Yes
2																			
3																			
4																			
5																			
6																			
Defects	/ Identi	fied								Labels a	and Warning No	otice Issued	CO Alarm(s)		Smoke	e Alarm(s)	
1											NA								
2													CO Alarm(s) fi	tted	Yes	Smoke	Alarm(s) fit	ted	NA
3																			
4												CO Alarm(s) tested and Satisfactory Pass			Smoke Alarm(s) tested and Satisfactory NA				
	5									and Satisfactory				and Satisfactory					
Emerger	ıcv Control	Accessible Yes G	as Tightness Sa	atisfactory Yes	<u> </u>	Com	ments												
			_		3														
Gas Installation Pipework Visual Inspection Satisfactory Yes																			
Equipotential Bonding Yes																			
Water or	ıality/lovol	of inhibitor acceptab	lo NA																
,	-																		
NEXT IN	ISPECTIO	N DUE BEFORE	05-Aug-202	25															
Signatu	res																		
Issued b		gned BM	1 aul			teceived !	Signed						Date	05-A	ug-2024				
		1_000	Lea			· , ·													