

Landlord Gas Safety Record

Cert. No. 525

Gas and heating specialists

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure.

Company / Installer							Job Address							Customer / Landlord						
Engineer Company		Steven Ballard				Name							Name							
		Ballards gas services ltd				Address	57					Company	Condor Properties							
Addres		201					Radmoor Road					Address	mill house							
		Sileby Road					Loughborough						Lugg Bridge Mill							
		Barrow Upon Soar						Leicestershire					Worcester Road							
		Leicestershire				Post Code		LE11 3BP						Hereford						
Post Code		LE12 8LP			Tel. No								HR1 3NA							
Tel No.		07599610379										Tel. No								
Gas Safe Reg																				
ID Card No.		321301																		
Appliance Details Inspection Details																				
Αρριια	Location					Inspection Details Flue Type Landlord's Appliance Inspected							on Low Combustion	Visual condition Flue Appliance Appliance safe						
	Location		Appliance Type	Make	Мод	eı	Flue Ty	pe Landlord's Appliance	Appliance inspected	Operating Pressure (mbar)	Heat Input (kw/n)	Reading	Reading CO2 Ratio CO CO	correct operation	Ventilation Provision satisfactory	of flue and termination satisfactory	Performance test	Serviced	to use	
	tility Ro	om	Combination Boiler	Ideal	Logic	30+	RS	Yes	Yes	20	28.3		9.2 0001 13 8.		Yes	Yes	Pass	Yes	Yes	
2																				
3																				
4																				
5																				
6			_																	
		dentified						Labels and Warning Notice Issued			CO Alarm(s)		Smoke	Alarm(s)				
											NA		CO Alarm(s) fi	ttod.	Yes	Cmaka	Alarm(s) fit	-ad	NA	
	3												CO Alaitii(S) II	iteu	165	Silloke	Alailii(S) iiti	.eu	IVA	
4												CO Alarm(s) tested		Smoke Alarm(s) tested						
5											and 9			nd Satisfactory Pass			and Satisfactory			
	6																			
Emerg	ency Cor	ntrol Ac	cessible Yes Gas	Tightness Satisfactory Ye	es	Comi	ment	S												
Gas Installation Pipework Visual Inspection Satisfactory Yes																				
Equipotential Bonding Yes																				
Water quality/level of inhibitor acceptable NA																				
NEXT	INSPEC	TION D	UE BEFORE	05-Aug-2025																
Signa	ures																			
Issued by: Signed Received Signed by: Date 05-Aug-2024 by:																				
Print Name Steven Ballard Print Name																				