

Landlord Gas Safety Record

Cert. No. 519

Gas and heating specialists

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure.

Company / I	nstaller				Job Addı	ress						Customer / l	andlord						
Engineer	Steven Ballard				Name							Name							
Company	Ballards gas services ltd					Address 6							Condor Properties						
Address 201						PI	easant Cl	ose				Address	mill house						
	Sileby Road					Lo	Loughborough						Lugg Bridge Mill						
					eicestersh	ire					Worcester Road								
	Barrow Upon Soar Leicestershire				Post Code	e LE	LE11 5BE					Hereford							
Post Code LE12 8LP					Tel. No							Post Code	HR1 3NA						
Tel No. 07599610379												Tel. No							
Gas Safe Reg 527987																			
ID Card No.																			
Appliance Details Inspection Details																			
Location	Appliance	Туре	Make	Mod	el	Flue Type	Landlord's Appliance	Appliance Inspected	Operating Pressure (mbar)	Heat Input (kW/h)	High Combusti Reading	on Low Combustion Reading	Safety device(s correct) Ventilation Provision	Visual condition of flue and	Flue Performance	Appliance Serviced	Appliance safe to use	
							Appliance		(IIIDai)		Ratio CO	CO2 Ratio CO CC	operation	satisfactory	termination satisfactory	test	Serviced	to use	
1 1/2	- Complianti	D-il	141	Lauta 20	2 M	DC	V		21	20.7	ppm	% ppm %		V		D	V	V	
1 Kitcher	n Combinatio	on Boller	Ideal	Logic 30	J мах	RS	Yes	Yes	21	28.7	0012 101	9.6 0002 16 8.	9 Yes	Yes	Yes	Pass	Yes	Yes	
3																			
4																			
5																			
6																			
	1161								Laholca	and Warning No	atica Issued	CO Alamata	1		Curalis	Al/-	7		
Defects / Identified									Labels a	ind warming ive	CO Alarm(s	Smoke	Smoke Alarm(s)						
1										NA									
2										CO Alarm(s) fitted Yes			Smoke	Smoke Alarm(s) fitted NA					
	3																		
5										CO Alarm(s) tested and Satisfactory Pass			Smoke Alarm(s) tested and Satisfactory NA						
6											and Satisfacto	' y		una sat	isiactory				
_					Com	monto													
Emergency Cor	ntrol Accessible Ye	es Gas T	ightness Satisfactory Yes	S	Comi	ments													
Gas Installation	n Pipework Visual II	nspection S	Satisfactory Yes																
Farrington	ial Bandina Vaa																		
Equipotential Bonding Yes																			
Water quality/l	evel of inhibitor ac	ceptable	NA																
NEYT INSDEC	TION DUE BEFOR	F	05-Aug-2025																
NEXT INSTEC	TION DOL DEI ON	` _	00 / kg 2020																
Signatures																			
Issued by:						Signed						Date 05-Aug-2024							
	1-	MNeu	U	k	by:														
Print Name	Steve	en Ballard		F	Print Name														