



Landlord Gas Safety Record

Cert. No. 521

Gas and heating specialists

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations 1998 section 26(9) and the Gas Industry Unsafe Situations Procedure.

Company / Installer

EngineerSteven Ballard

CompanyBallards gas services ltd

Address201
Sileby Road
Barrow Upon Soar
Leicestershire

Post CodeLE12 8LP

Tel No.07599610379

Gas Safe Reg527987

ID Card No.

Job Address

Name

Address68
Derby Road
Loughborough
Leicestershire

Post CodeLE11 5BX

Tel. No

Customer / Landlord

Name

CompanyCondor Properties

Addressmill house
Lugg Bridge Mill
Worcester Road
Hereford

Post CodeHR1 3NA

Tel. No

| Appliance Details | | | | | | Inspection Details | | | | | | | | | | | | | | | |
|-------------------|----------|--------------------|-------|--------------|-----------|----------------------|---------------------|---------------------------|-------------------|-------------------------|--------|-------|------------------------|--------|-------|------------------------------------|------------------------------------|---|-----------------------|--------------------|-----------------------|
| | Location | Appliance Type | Make | Model | Flue Type | Landlord's Appliance | Appliance Inspected | Operating Pressure (mbar) | Heat Input (kW/h) | High Combustion Reading | | | Low Combustion Reading | | | Safety device(s) correct operation | Ventilation Provision satisfactory | Visual condition of flue and termination satisfactory | Flue Performance test | Appliance Serviced | Appliance safe to use |
| | | | | | | | | | | Ratio | CO ppm | CO2 % | Ratio | CO ppm | CO2 % | | | | | | |
| 1 | Kitchen | COMBINATION BOILER | Ideal | Logic Max 30 | RS | Yes | Yes | 21.5 | 29.25 | 0007 | 101 | 9.0 | 0001 | 14 | 8.6 | Yes | Yes | Yes | Pass | No | Yes |
| 2 | | | | | | | | | | | | | | | | | | | | | |
| 3 | | | | | | | | | | | | | | | | | | | | | |
| 4 | | | | | | | | | | | | | | | | | | | | | |
| 5 | | | | | | | | | | | | | | | | | | | | | |
| 6 | | | | | | | | | | | | | | | | | | | | | |

Defects / Identified

1

2

3

4

5

6

Labels and Warning Notice Issued

NA

CO Alarm(s)

CO Alarm(s) fitted

CO Alarm(s) tested and Satisfactory

Yes

Pass

Optional Checks

Smoke Alarm(s) fitted

Smoke Alarm(s) tested and Satisfactory

Water quality/level of inhibitor acceptable

NA

NA

NA

Emergency Control Accessible YesGas Tightness Satisfactory Yes

Gas Installation Pipework Visual Inspection Satisfactory Yes

Equipotential Bonding Yes

NEXT INSPECTION DUE BEFORE27-Aug-2026

Comments

Signatures

Issued by:Signed

Print NameSteven Ballard

Received by:Signed

Print Name

Date27-Aug-2025