

Landlord Gas Safety Record

Cert. No. 537

Gas and heating specialists

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations 1998 section 26(9) and the Gas Industry Unsafe Situations Procedure.

							maaser.	y orisare sicuati	ons moccaure.									
Company / I	Installer				Job Addr	ess						Customer / I	_andlord					
Engineer	Steven Ballard				Name							Name						
Company	Ballards gas services ltd				Address	72	72					Company	Condor Properties					
Address 201				Oxford Street						Address mill house								
	Sileby Road						Loughborough						Lugg Bridge Mill					
	Barrow Upon Soar					Le	Leicestershire						Worcester Road					
	Leicestershire				Post Code	LE	LE11 5DR						Hereford					
Post Code					Tel. No							Post Code	HR1 3NA					
Tel No.												Tel. No						
	07555010575																	
Gas Safe Reg 527987 ID Card No.																		
Appliance D	etails						Inspec	tion Details	5									
Location	n Appliance	Туре	Make	Mode	el	Flue Type	Landlord's Appliance	Appliance Inspected	Operating Pressure (mbar)	Heat Input (kW/h)	High Combustion Reading	on Low Combustion Reading	Safety device(s) correct	Ventilation Provision	Visual condition	n Flue Performance	Appliance Serviced	Appliance safe to use
							"					CO2 Ratio CO CO	operation	satisfactory	termination satisfactory	test		
1 Kitche	en Combinatio	n Boiler	Ideal	Vogue	C32	RS	Yes	Yes	22	31		9.4 0001 17 8.		Yes	Yes	Pass	Yes	Yes
2																		
3																		
4																		
5																		
6																		
Defects / Ide	entified								Labels a	and Warning No	otice Issued	CO Alarm(s)		Option	al Check	(S	
1										NA		CO Alarm(s) fi	tted	Yes	Smoke	Alarm(s) fit	ted	NA
2										IVA								
3												CO Alarm(s) to		Pass		Alarm(s) te	sted	NA
4												and Satisfacto	ory	. 455	and Sa	tisfactory		
5															Water	quality/leve	l of inhihito	
6															accepta		ו טו ווווווטונט	NA NA
Emergency Co	ontrol Accessible Ye	Gas Tightn	ess Satisfactory Ye	S	Comr	nents												
Gas Installatio	n Pipework Visual Ir	spection Satisfa	actory Yes															
Gus mstanatio	in ripework visual ii	ispection sutisie	accory res															
Equipotent	tial Bonding Yes																	
NEXT INSPEC	TION DUE BEFOR	E 05-Au	ug-2026															
			_															
Signatures																		
Issued by:	Signed R				Received Signed								Date 05-Aug-2025					
	1/-	Balleul		k	oy:													
Print Name	Steve	n Ballard		F	Print Name													