

Landlord Gas Safety Record

Cert. No. 523

Gas and heating specialists

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure.

Company / Installer					Job Address							Customer / Landlord									
Engineer		Steven Ba	Name							Name											
Company Address		Ballards g	Address	75						Company	Co	ondor Prop	erties								
		201		Storer Road					Address	m	mill house										
		Sileby Ro		Lo	Loughborough						Lu	Lugg Bridge Mill									
		Barrow Upon Soar					Le	Leicestershire						W	Worcester Road						
		Leicestershire				Post Code	LE	LE11 5EH						Не	Hereford						
Post Code		LE12 8LP				Tel. No							Post Code	HF	HR1 3NA						
Tel No.		07599610379											Tel. No								
Gas Safe Reg																					
ID Card No.																					
۸n	pliance D	otails						Inspec	ction Details												
¬μ	Location					el F	lue Type	Landlord's		Onerating Pressure	Heat Input (kW/h)	High Combusti	on Low Combu	ıstion S	Safety device(s)	Ventilation	Visual condition	Flue	Appliance	Appliance safe	
	Location		Appliance Type	Hanc	1100		ide i ype	Appliance	7.pp.idirec inspected	(mbar)	Treat input (KTI)II)	Reading	Reading	g	correct operation	Provision satisfactory	of flue and termination	Performance test	Serviced	to use	
												Ratio CO (CO2 Ratio CO ppm		operation	Satisfactory	satisfactory	test			
1	Bedroon	ns Co	mbination Boiler	Ideal	Logic	30+	RS	Yes	Yes	21	29	0007 97 9	9.3 0001 27	8.9	Yes	Yes	Yes	Pass	Yes	Yes	
2																					
3																					
4																					
5																					
6																					
De	fects / lde	entified		Lab				and Warning No	CO Alarm	า(ร)			Smoke	Alarm(s	ı						
	1								NA												
2												CO Alarm(s) fitted Yes			Smoke /	Smoke Alarm(s) fitted NA					
3													CO Alarm(s) tested			Smoke	Smoke Alarm(s) tested				
5													and Satisfactory		eu	Pass	and Satisfactory		iteu	NA	
	6													-				-			
Em	nergency Co	ntrol Acces	ssible Yes Gas	Tightness Satisfactory Yes	S	Comm	ents														
Gas Installation Pipework Visual Inspection Satisfactory Yes ECV falls into on position																					
Ga		•	•	Satisfactory Tes																	
	Equipotenti	al Bonding	Yes																		
Wa	ater quality/l	evel of inhi	ibitor acceptable	NA																	
			·	05-Aug-2025																	
NE	XT INSPEC	HON DUE	BEFORE	05-Aug-2025																	
Sig	gnatures																				
Issued by:		Cianad				Received Sig	gned						Date 05-Aug-2024								
			Banda	W	k	by:															
Pri	nt Name		Steven Ballard			Print Name															
	THE INCHITE		Steven buildiu			THE INDIFFE															