

Landlord Gas Safety Record

Cert. No. 534

Gas and heating specialists

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure.

Company / Installer					Job Addre	ess						Customer	/ Land	lord							
Engineer		Steven Ballard				Name								Name							
Company Address		Ballards gas services ltd				Address	9	94					Company	Cond	Condor Properties						
		201						Derby Road					Address	mill h	mill house						
	Sileby Road				L		Loughborough						Lugg	Lugg Bridge Mill							
		Barrow Upon Soar					L	Leicestershire						Word	Worcester Road						
	Leicestershire			Post Code	L	LE11 5AG					Post Code	Here	Hereford								
Post Code		LE12 8LP			Tel. No							HR1	HR1 3NA								
Tel No.		07599610379										Tel. No									
Gas Safe Reg																					
ID Card No.																					
Appliance Details Inspection Details																					
Аррпа	Location				Mode	el	Flue Typ	Inspection Details Type Landlord's Appliance Inspected Operating Pressure Heat Input (kW/h) High Combusti					ion Low Combi	ustion Safet	v device(s)	Ventilation	Visual condition	tion Flue	Appliance	Appliance safe	
	Location		Appliance Type	Muke	Hous		ride ryp	Appliance	Арриинсе пізрессей	(mbar)	ricat input (kwyny	Reading	Readin	CO2 op	correct peration	Provision satisfactory	of flue and termination satisfactory	Performance test	Serviced	to use	
1	Bedroon	ns	Combination Boiler	Glow-worm	Easico	m 28	RS	Yes	Yes	22	27.4		9.0 na na	-	Yes	Yes	Yes	Pass	Yes	Yes	
2																					
3																					
4																					
5																					
6			_										_				_				
Defect		entifie	d							Labels a	nd Warning N	otice Issued	CO Alarm	n(s)			Smoke	Alarm(s)		
	2										NA		CO Alarm(s	c) fitted		Yes	Smoko	Alarm(s) fit	-od	NA	
	3												CO Alaimi.	3) IIIIII		163	Silloke	Alaitii(3) iid	.cu	IVA	
4													CO Alarm(s	s) tested		Dage	Smoke	Alarm(s) tes	sted	NΑ	
5												and Satisfa	actory		Pass	and Satisfactory NA					
	6																				
Emerge	ency Co	ntrol Aco	cessible Yes Gas	Tightness Satisfactory Yes	S	Comm	nents														
Gas Ins	stallation	n Pipewo	ork Visual Inspection	Satisfactory Yes																	
Equ	uipotenti	ial Bond	ing Yes																		
Water quality/level of inhibitor acceptable NA																					
NEXT INSPECTION DUE BEFORE 05-Aug-2025																					
Signat Issued		Signed	d Banla	ul	k	Received Si by:	igned						Date		05-Au	ıg-2024					
Print N	ame		Steven Ballard		F	Print Name															