

Landlord Gas Safety Record

Cert. No. 534

Gas and heating specialists

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations 1998 section 26(9) and the Gas Industry Unsafe Situations Procedure.

Company / Installer							Job Address						Customer / Landlord								
Engineer Company Address		Steven Ballard Ballards gas services ltd 201 Sileby Road				Name							Nam	ie							
						Address	9	94					Com	pany	Condor Pro	perties					
							Derby Road					Addr	ress	mill house							
							L	Loughborough							Lugg Bridge Mill						
		Barrow Upon Soar					L	Leicestershire							Worcester	Worcester Road					
		Leicestershire				Post Code	L	LE11 5AG							Hereford						
		LE12 8LP				Tel. No							Post Cod	Code	HR1 3NA						
Tel No.		07599610379											Tel.	No							
Gas Safe Reg																					
ID Card No.		32,307																			
Appliance Details									tion Details												
	Locatio	in	Appliance Type	Make	Mod	el Flue	Flue Type	e Landlord's Appliance	ndlord's Appliance Inspected opliance	Operating Pressure (mbar)	Heat Input (kW/h)	High Combus Reading			correct	Provision	Visual condition of flue and	Performance	Appliance Serviced	Appliance safe to use	
												Ratio CO ppm	CO2 % Ra	atio CO C	O2 operation %	satisfactory	termination satisfactory	test			
1	Bedroo	ms	Combination Boiler	Glow-worm	Easico	m 28	RS	Yes	Yes	22	27.4	0002 21	9.0 n			Yes	Yes	Pass	Yes	Yes	
2																					
3																					
4																					
5																					
6																					
Defects / Identified								Labels and Warning Notice Issued					CO	CO Alarm(s)				Optional Checks			
	1	Condense discharge not to regulations							NA			CO Alarm(s) fitted Yes			Smoke	Smoke Alarm(s) fitted NA					
2														A I = (= \)	l		Constant	Al (-) +-	-41		
3												CO Alarm(s) tested Pass and Satisfactory				Smoke Alarm(s) tested and Satisfactory NA					
4 5														and Satisfactory				and Satisfactory			
6																		Water quality/level of inhibitor NA			
																		acceptable			
Er	nergency Co	ontrol Ad	ccessible <mark>Yes Gas</mark>	Tightness Satisfactory Ye	s	Comm	nents														
Gas Installation Pipework Visual Inspection Satisfactory Yes																					
Ga	is installatio	on Pipew	ork visual inspection	Satisfactory Yes																	
	Equipoten	tial Bond	ding Yes																		
NEXT INSPECTION DUE BEFORE 06-Aug-2026																					
	LXI IIIGI E		JOE DEI ONE																		
Sic	gnatures																				
	sued by:	Signe	ed 10	/	F	Received S	igned					D	ate	06-Aug-2025							
			Balle	W	k	oy:															
_	int Name																				
Pr	uu Name		Steven Rallard			Print Name															