

## **Landlord Gas Safety Record**

Cert. No. 539

Gas and heating specialists

Steven Ballard

Print Name

Print Name

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure.

Company / I		Job Address							Customer / Landlord									
Engineer	Steven B	Steven Ballard										Name						
Company	Ballards	Ballards gas services ltd				Address 96						Company	Condor Properties					
Address	201					Derby Road						Address	mill house					
	Sileby Road					Lo	Loughborough						Lugg Bridge Mill					
	Barrow U		Le	eicestersh	nire					Worcester R	oad							
	Leicestershire				Post Code	LE	LE11 5AG						Hereford					
Post Code							Post Code HR1 3NA											
Tel No.	LETE OLI											Tel. No						
Gas Safe Reg	07333010373																	
ID Card No.																		
Appliance D								tion Details										
Location	1	Appliance Type	Make	Mode	el	Flue Type	Landlord's Appliance	Appliance Inspected	Operating Pressure (mbar)	Heat Input (kW/h)	High Combusti Reading	on Low Combustion Reading	correct	Provision	Visual condition of flue and	Flue Performance	Appliance Serviced	Appliance safe to use
												CO2 Ratio CO CO % ppm %		satisfactory	termination satisfactory	test		
1 Loung	e (	Central Heating Boiler	Ideal	Logic Sys	tem 30	RS	Yes	Yes	22	28.6		9.7 0001 14 8.		Yes	Yes	Pass	Yes	Yes
2		Donei																
3																		
4																		
5																		
6																		
Defects / Identified CO Alarm(s) Smoke Alarm(s)																		
Defects / fac									eo marm(s	1		Sirioke	7 (Idimi(5)	4				
1										NA								
2												CO Alarm(s) fitted Yes		Smoke Alarm(s) fitted NA				
4												CO Alarm(s) tested		Smoke Alarm(s) tested				
5												and Satisfactory			and Satisfactory NA			
6																		
Emergency Control Accessible Yes Gas Tightness Satisfactory Yes Comments																		
S / Cas rigillates statistically less																		
Gas Installation Pipework Visual Inspection Satisfactory Yes																		
Equipotent	tial Bondin	g Yes																
Water quality/	loval of inh	ibitor acceptable	NΑ															
water quality/	ievei oi iiii	libitor acceptable																
NEXT INSPECTION DUE BEFORE 05-Aug-2025																		
Signatures																		
Issued by:	Signed	10	,	F	Received S	Signed						Date	05-A	ug-2024				
		Balla	rul	b	y:													