



# Homeowner / Landlord Gas Safety Record

Cert No.  
No. 0537

No. Appliances  
1

This inspection is for gas safety purposes only to comply with the Gas Safety (Installation and Use) Regulations. Flues have been inspected visually and checked for satisfactory evacuation of products of combustion. A detailed internal inspection of the flue integrity, construction and lining has NOT been carried out.  
Registered Business/engineer details can be checked at [www.gassaferegister.co.uk](http://www.gassaferegister.co.uk) or by calling 0800 408 5500

Company / Installer										Inspection / Installation Address										Landlord / Agent / Customer											
Engineer		Mark Robins								Name										Name											
Company		SMK Plumbing & Heating Ltd								Address		67 Mansel Street Swansea								Company Name		Condor properties									
Address		8 Glan Yr Afon Road, Sketty, Swansea, SA2 9JE								Postcode		SA1 5TN								Address		Mill house Worcester road Hereford									
Tel No.		07917177113								Mobile										Postcode		HR1 3NA									
Gas Safe Reg.		509889								Email										Email		Ryan@condorproperties.co.uk									
ID Card No.		5609907								Unique Property Reference Number										Phone											
Email		robins22@hotmail.com																		Unique Property Reference Number											
Appliance Details										Flue Tests										Inspection Details											
#	Location	Make	Model	Type	Serial No	Flue Type	Operating pressure (mBar) or heat input (kW/h or Btu/h)	Safety Device(s) correct operation	Spillage test	Smoke Pellet Flue Flow Test	Initial (low) combustion analyser reading			Final (high) Combustion analyser reading			Satisfactory Termination	Flue visual condition	Adequate ventilation	Landlord's appliance	Inspected	Appliance visual check	Appliance serviced	Appliance safe to use							
											Ratio	CO ppm	CO2 (%)	Ratio	CO ppm	CO2 (%)															
1	Compartment	WORCESTER	Worcester Greenstar 18Ri Erp	Combination Boiler		RS	18kw	Yes	N/A	N/A				0.0007	76	9.0	Yes	Pass	Yes	Yes	Yes	Yes	No	Yes							
2																															
3																															
4																															
5																															
Gas Installation Pipework										Audible CO Alarms																					
Satisfactory Visual Inspection				Emergency Control Accessible				Satisfactory Gas Tightness Test				Equipotential Bonding Satisfaction				Approved CO Alarms Fitted				Are CO Alarms in Date				Testing CO Alarms				Smoke Alarms Fitted			
Yes	✓			Yes	✓			Yes	✓					Yes	✓			Yes	✓			Yes	✓								
No	–			No	–			No	–					No	–			No	–			No	–								
N/A	–			N/A	–			N/A	–					N/A	–			N/A	–			N/A	–								
Give Details of Any Faults										Rectification Work Carried Out																					
Details of Works																															
Has flue cap been put back?																															
Yes																															
Signatures																															
Signed								Received By								Date		18-03-2024													
Print Name		Mark Robins						Print Name		–						Next Inspection Date		18/03/2025													