

Homeowner / Landlord Gas Safety Record



This inspection is for gas safety purposes only to comply with the Gas Safety (Installation and Use) Regulations. Flues have been inspected visually and checked for satisfactory evacuation of products of combustion. A detailed internal inspection of the flue integrity, construction and lining has NOT been carried out. Registered Business/engineer details can be checked at www.gassaferegister.co.uk or by calling 0800 408 5500

Company / Installer								Inspectio	Inspection / Installation Address									Landlord / Agent / Customer							
Engineer Mark Robins						Name	Name									Name									
Company		SMK Plumb	SMK Plumbing & Heating Ltd						Address					272 Oystermouth Road				Company Name				Condor properties			
Address		8 Glan Yr A	8 Glan Yr Afon Road, Sketty, Swansea, SA2 9JE											Swansea				Address				Mill house Worcester road			
Tel No.		079171771	07917177113						Postcode Mobile					SA1 3UH				Postcode				Hereford HR1 3NA			
Gas Safe Reg.		509889							Landline									Email				Ryan@condorproperties.co.uk			
ID Card No.		5609907						Email									Phone								
Email		robins22@h	hotmail.com					Unique Pr	Unique Property Reference Number								Unique Property Reference Number								
			Appliance Details						Flue Tests									Inspection Details							
					Flue	Operating pressure (mBar) or		Safety Device(s)	Spillage		Initial (low) comb	ustion	Final (high) Co		bustion	Satisfactory	Flue visual	Adequate	Landlord's		Appliance	Appliance	Appliance safe		
# Location Make M		Model	lodel Type		Туре			correct operation	test	Flue Flow Test	analyser reading			r reading		Termination	condition	ventilation	appliance	Inspected		serviced	to use		
											Ratio CO ppm	CO2 (%	b) Ratio	CO pp	m CO2 (%)									
1 Utility Room	VAILLANT	Vaillant ecoTEC pro 28	Combination Boiler		RS	28kw		Yes	N/A	N/A			0.0014	130	9.0	Yes	Pass	Yes	Yes	Yes	Yes	No	Yes		
2																									
3																									
4																									
5																									
5																									
Gas Installatio	n Pipework											Audible Co													
Satisfactory Visual Inspection		n	Emergency Control Accessible			Satisfactory Gas Tight				ential Bonding Satisfac			oved CO Alarms Fitted				Are CO Alarms in Date		Testing CO Alarms		Smoke Alarms Fitted				
Yes 🗸			Yes 🗸				es 🗸		Yes	1		Yes 🗸				Yes 🗸			1		Yes	/			
No _			No _			N	-		No	-		No _				No _		No	-		No	-			
N/A _			N/A _			N	/A _		N/A _			N/A _ N/A _				N/A _	N/A _			N/A _					
Gi						etails of Any Fa	ults										Rectification Work Carried Out								
											Details of	Works													
											Has flue cap bee	n nut haci	k2												
Yes											has had dap bee	in put baci													
Signatures																									
- griditaroo																									
Signed			\sim			·		Received By	red By				Date							18-03-2025					
						~							Dute												
Print Name			Mark Robins					Print Name	int Name				Next			Next Inspection	Date			18/03/2026					