

## Homeowner / Landlord Gas Safety Record

Cert No. No. 1056 No. Appliances

This inspection is for gas safety purposes only to comply with the Gas Safety (Installation and Use) Regulations. Flues have been inspected visually and checked for satisfactory evacuation of products of combustion. A detailed internal inspection of the flue integrity, construction and lining has NOT been carried out.

Registered Business/engineer details can be checked at www.gassaferegister.co.uk or by calling 0800 408 5500

Company / Installer							Inspection	Inspection / Installation Address									Landlord / Agent / Customer								
ng	jineer		Mark Robins					Name						Name											
Company			SMK Plumbing & Heating Ltd						Address	Address					324 Oystermouth Road				Company Name				Condor properties		
dd	Iress		8 Glan Yr Afon Road, Sketty, Swansea, SA2 9JE						D4d-	Destroyle					Swansea				Address				Mill house Worcester road		
el No.			07917177113						Mobile	Postcode					SA1 3UJ				Postcode				HR1 3NA		
as Safe Reg.			509889						Landline									Email				Ryan@condorproperties.co.uk			
Card No.			5609907					Email									Phone				ryang condorproportion of the				
ma	ail		robins22@hotmail.com						Unique Property Reference Number									Unique Property Reference Number							
			Appliance Details						Flue Tests									Inspection Details							
	Location	Make	Serial Flue Operating pressure (mBar) or Model Type No Type heat input (kW/h or Btu/h)				Spillage	Smoke Pellet Flue Flow Test	Initial (low) combi	ustion	Final (high) Combustion Satisfactory analyser reading Termination				Adequate ventilation	Landlord's appliance		Appliance visual check	Appliance	Appliance safe					
	Location	Make	Model	туре	NO	туре	neat input (	KW/II OF BIU/II)	correct operation	test	Fide Flow Test	analyser reading		anary	serreading		Termination	Condition	ventilation	аррпансе	inspecteu	VISUAI CHECK	serviced	to use	
												Ratio CO ppm	CO2 (%)	Ratio	CO ppn	CO2 1 (%)									
-	Kitchen	WORCESTER		Combination Boiler		RS	42kw		Yes	N/A	N/A			0.001	0 85	9.2	Yes	Pass	Yes	Yes	Yes	Yes	No	Yes	
2																									
3																									
'																									
ot	iofooton ( ) (	aual Inspection	Emergency Control Accessible Satisfactory Gas Tightness						n Toot	Test Equipotential Bonding Satisfaction Approve					ed CO Alarms Fitted Are CO Alarm				ns in Date Testing CO Alarms				Smoke Alarms Fitted		
Satisfactory Visual Inspection  Ves			Yes ✓				Yes	, ,	is lest	Yes /		Ye.					Yes ✓			Yes ✓		Yes /			
No.			No				No	•		No No		No					No		No	•		No _			
								-		-							_			-					
N/A	· –		N/.	N/A _ N/A _					N/A N/A					_ N/A _				N/A _				N/A _			
Give Details of Any Faults																	Rectification								
												Details of Wo	rks												
												Has flue cap been p	ut back?												
es/	5																								
an:	atures																								
9																									
Signed			Rec					nived Dv					Date								19.02.2025				
Signed			Rec					ссией Бу	eived By					Date								18-03-2025			
Print Name			Mark Robins Print						int Name					Next Inspection Date				Date	te				18/03/2026		