

Homeowner / Landlord Gas Safety Record

Cert No.
No. 1068
No. Appliances

This inspection is for gas safety purposes only to comply with the Gas Safety (Installation and Use) Regulations. Flues have been inspected visually and checked for satisfactory evacuation of products of combustion. A detailed internal inspection of the flue integrity, construction and lining has NOT been carried out.

Registered Business/engineer details can be checked at www.gassaferegister.co.uk or by calling 0800 408 5500

Company / Installer								Inspection / Installation Address										Landlord / Agent / Customer								
Engineer		Mark I	Robins				Name	Name									Name									
Company		SMK I	Plumbing & Heating L	_td			Address											mpany Name		Condor properties						
Address		8 Glar	Yr Afon Road, Skett	ty, Swanse	a, SA2 9JE									Swansea				Idress		Mill house Worcester road						
Tel No.			177113											SA1 4LL						Hereford						
Gas Safe Re		50988						Mobile										stcode		HR1 3NA						
ID Card No.		56099						Landline Email											Email Phone				Ryan@condorproperties.co.uk			
Email			22@hotmail.com					Unique Property Reference Number						Unique Property Reference Number												
			Appliance Details							Flue Tests									Inspection Details							
# Location	Location Make Model		Туре	Serial No	Flue Type	Operating pressure (mBar) or heat input (kW/h or Btu/h)	Safety Device(s) correct operation	Spillage test	Smoke Pellet Flue Flow Test		(low) combus er reading	v) combustion reading		Final (high) Combustion		Satisfactory Termination		Flue visual condition	Adequate ventilation	Landlord's appliance	Inspected	Appliance visual check	Appliance serviced	Appliance safe to use		
										Ratio	CO ppm	CO2 (%) Ratio	COp	pm CO2 (%)											
1 Kitchen	BAXI	Platinum compact 30 combi	Combination Boiler		RS	30kw	Yes	N/A	N/A				0.0008	72	8.9	Yes		Pass	Yes	Yes	Yes	Yes	No	Yes		
2																										
2																										
4																										
5																										
Gas Installati																										
Satisfactory Visual Inspection		spection	Emergency Control Accessible			Satisfactory Gas T	ghtness Test	Equipotential Bonding Satisfaction				Approve	Approved CO Alarms Fitted			Are CO Alarms in Date		Testing CO Alarms			Smoke Alarms Fitted					
Yes 🗸	·		Yes 🗸			Yes 🗸	Yes		1			Yes	s /		Yes 🗸		Yes		1		Yes	/				
No _			No _			No _		No	_			No	_			No	_		No	_		No	_			
N/A _			N/A _			N/A _		N/A				N/A				N/A	_		N/A	_		N/A				
				Give	Details of Any Faults													tification Work Carried Out								
					0.110	Dotails of 7111y Faults												rtootmoution	· Work ourned ou							
											Details of	Works														
										Has	flue cap bee	en put ba	ck?													
Yes	Has flue cap been put back? Yes																									
Signatures																										
Janataroo																										
Signed						Received By		1							Date				19-03-2025							
Print Name					Mark Ro	bbins	Print Name			_					Next Inspe				Inspection Date				19/03/2026			