



Homeowner / Landlord Gas Safety Record

Cert No.
No. 1076

No. Appliances
1

This inspection is for gas safety purposes only to comply with the Gas Safety (Installation and Use) Regulations. Flues have been inspected visually and checked for satisfactory evacuation of products of combustion. A detailed internal inspection of the flue integrity, construction and lining has NOT been carried out.
Registered Business/engineer details can be checked at www.gassaferegister.co.uk or by calling 0800 408 5500


Company / Installer						Inspection / Installation Address						Landlord / Agent / Customer					
Engineer	Mark Robins					Name						Name					
Company	SMK Plumbing & Heating Ltd					Address	8 Rhondda Street Swansea					Company Name	Condor properties				
Address	8 Glan Yr Afon Road, Sketty, Swansea, SA2 9JE					Postcode	SA1 6ER					Address	Mill house Worcester road Hereford				
Tel No.	07917177113					Mobile						Postcode	HR1 3NA				
Gas Safe Reg.	509889					Landline						Email	Ryan@condorproperties.co.uk				
ID Card No.	5609907					Email						Phone					
Email	robins22@hotmail.com					Unique Property Reference Number						Unique Property Reference Number					

Appliance Details								Flue Tests						Inspection Details										
#	Location	Make	Model	Type	Serial No	Flue Type	Operating pressure (mBar) or heat input (kW/h or Btu/h)	Safety Device(s) correct operation	Spillage test	Smoke Pellet Flue Flow Test	Initial (low) combustion analyser reading			Final (high) Combustion analyser reading			Satisfactory Termination	Flue visual condition	Adequate ventilation	Landlord's appliance	Inspected	Appliance visual check	Appliance serviced	Appliance safe to use
											Ratio	CO ppm	CO2 (%)	Ratio	CO ppm	CO2 (%)								
1	Kitchen	IDEAL	Ideal Independent C30	Combination Boiler		RS	30kw	Yes	N/A	N/A				0.0015	129	8.7	Yes	Pass	Yes	Yes	Yes	Yes	No	Yes
2																								
3																								
4																								
5																								
Safety Installation Inspection												Appliance CO Alarms												
Satisfactory Visual Inspection				Emergency Control Accessible			Satisfactory Gas Tightness Test			Equipotential Bonding Satisfaction			Approved CO Alarms Fitted			Are CO Alarms in Date			Testing CO Alarms			Smoke Alarms Fitted		
Yes	✓			Yes	✓		Yes	✓		Yes	✓		Yes	✓		Yes	✓		Yes	✓		Yes	✓	
No	—			No	—		No	—		No	—		No	—		No	—		No	—		No	—	
N/A	—			N/A	—		N/A	—		N/A	—		N/A	—		N/A	—		N/A	—		N/A	—	

Give Details of Any Faults	Rectification Work Carried Out

Details of Works

Has flue cap been put back?
Yes

Signatures					
Signed		Received By		Date	21/03/2025
Print Name	Mark Robins	Print Name	—	Next Inspection Date	21/03/2026