

Homeowner / Landlord Gas Safety Record

Cert No. No. 1071 No. Appliances

This inspection is for gas safety purposes only to comply with the Gas Safety (Installation and Use) Regulations. Flues have been inspected visually and checked for satisfactory evacuation of products of combustion. A detailed internal inspection of the flue integrity, construction and lining has NOT been carried out.

Registered Business/engineer details can be checked at www.gassaferegister.co.uk or by calling 0800 408 5500

C	Company / Installer					Inspection	Inspection / Installation Address								Landlord / Agent / Customer						
		Mark Robins			Name							Name									
	ngineer ompany	SMK Plumbing & Heating Ltd									Flat B 388, Oystermouth Road							Condor properties			
		8 Glan Yr Afo		71441055					Swansea				Company Name Address				Mill house Worcester road				
		07917177113						SA1 3UL								Hereford					
	as Safe Reg.	509889		Mobile								Postcode				HR1 3NA					
	Card No.	5609907			Landline								Email				Ryan@condorproperties.co.uk				
		robins22@ho	tmail com		Email								Phone								
-	man	TODHISZZ@HO			Unique Prop	Unique Property Reference Number				Unique Property Reference Number											
Appliance Details							Flue Tests							Inspection	Details						
#	Location Make	Model	Type Serie	al Flue Type	Operating pressure (mBar) or heat input (kW/h or Btu/h)	Safety Device(s) correct operation	Spillage test	Smoke Pellet Flue Flow Test	Initial (low) combust analyser reading		(high) (ser rea	Combustion ding	Satisfactory Termination	Flue visual condition	Adequate ventilation	Landlord's appliance	Inspected	Appliance I visual check	Appliance serviced	Appliance safe to use	
									Ratio CO ppm	CO2 (%) Ratio	C	O ppm CO2 (%)									
1	Kitchen WORCESTER	Greenstar 25i erp	Combination Boiler	RS	25kw	Yes	N/A	N/A		0.000	9 88	9.1	Yes	Pass	Yes	Yes	Yes	Yes	No	Yes	
2																					
3																					
4																					
5																					
S	atisfactory Visual Inspection	Emergency Control Accessible Satisfactory Gas Tightness				ness Test	s Test Equipotential Bonding Satisfaction App				proved CO Alarms Fitted Are CO Alarm				ns in Date Testing CO Alarms				Smoke Alarms Fitted		
Yes 🗸		Yes 🗸			Yes 🗸		Yes 🗸		Yes	Yes 🗸		Yes 🗸		Yes		/		Yes 🗸			
N	lo _		No _		No _		No _		No	_			No _		No	_		No	_		
N	I/A _		N/A _		N/A _		N/A		N/A	_			N/A _		N/A	_		N/A	_		
		Give Details of Any Faults												Rectification Work Carried Out							
					,																
									Details of Wor	rks											
									Has flue cap been p	ut back?											
Υ	'es																				
Sic	gnatures																				
S	signed		C	me	-	Received By							Date					19-03-2	2025		
Р	rint Name	Mark Robins Print N			Print Name	Jame _						Next Inspection E	n Date				19/03/2026				