

Homeowner / Landlord Gas Safety Record



This inspection is for gas safety purposes only to comply with the Gas Safety (Installation and Use) Regulations. Flues have been inspected visually and checked for satisfactory evacuation of products of combustion. A detailed internal inspection of the flue integrity, construction and lining has NOT been carried out. Registered Business/engineer details can be checked at www.gassaferegister.co.uk or by calling 0800 408 5500

Company / Installer									Inspection / Installation Address									Landlord / Agent / Customer							
Engineer		Mark Robins					Name	Name								ne									
Company		SMK Plumbing & H					Address	Address				139 Bryn Road				mpany Name				Condor properties					
Address		8 Glan Yr Afon Roa	sea, SA2 9	JE			Postcode	Postcode					Swansea SA2 0UA				Address				Mill house Worcester road Hereford				
Tel No.		07917177113						Mobile					SAE OUA				Postcode				HR1 3NA				
Gas Safe Reg	I-	509889					Landline										Email				Ryan@condorproperties.co.uk				
ID Card No.		5609907						Email	Email				Ph				Phone				,				
Email		robins22@hotmail.					Unique Prope	Unique Property Reference Number				Unique Property Reference Number						er							
			Appliance Det	ails							Flue Tests								Inspection	n Details					
# Location	Make	Model	Туре	Serial No	Flue Type	Ope	erating pressure (mBar) at input (kW/h or Btu/h)	or Safety Device(s) correct operation	Spillage test		Initial (low) cor analyser readir	mbustion	Final (hi	Final (high) Combustion analyser reading		Satisfactory Termination	Flue visual condition	Adequate ventilation	Landlord's		Appliance d visual check	Appliance serviced	Appliance safe to use		
# Location	Make	Model	Type	NO	туре	neal I	at input (kw/n or Blu/n)	conect operation	lesi	Flue Flow Test				CO2		Termination	condition	ventilation	аррпансе	inspected	u visuai check	Serviceu			
											Ratio CO p	pm CO2 (%)		CO ppm											
1 Bathroom	WORCESTER	worcester Combination Greenstar 42CDi Boiler			RS	42kw		Yes	es N/A N/A				0.0009	103	9.2	Yes	Pass	Yes	Yes	Yes	Yes	No	Yes		
2																									
3																									
4																									
5																									
Gas Installat																									
Satisfactory \	isual Inspection	Emergency Control Accessible Satisfactory Gas Tightness					ess Test	Equipotential Bonding Satisfaction Approv				red CO Alarms Fitted Are CO Alarm				rms in Date Testing CO Alarms				Smoke Alarms Fitted					
Yes 🗸		Ye				Yes 🗸		Yes 🗸		Yes 🗸				Yes 🗸	Yes		s 🗸	/		/					
No _		N					No _		No	_		No _				No _		No	_		No	_			
N/A		N	'A _				N/A _		N/A	_		N/A				N/A _		N/	A _		N/A	_			
			Gi	ve Details	s of An	ny Faults	l.											Rectification Work Carried Out							
											Details of \	Works													
											Has flue cap bee	en put back?													
Yes																									
Signatures																									
Signed				\sim	ρ_{γ}	_		Received By								Date					20-03-20	025			
Print Name				Mark	Robins			Print Name								Next Inspection Date	9				20/03/20	026			